


Pos: 7; Schäden an Abdeckung oder Rahmen, anderer Schaden, Auflagering gemauert, nicht fachgerecht



94

Pos: 9; schadhafte Steighilfen, fehlendes Steigeisen, Anzahl = 2




95



95,1

Pos: 8; Schäden an Abdeckung oder Rahmen, anderer Schaden, Auflageringe zu hoch




96



100



295



303



305



1017



1021



1141



1145



1155



1665



1666



1668



1678



1681



2104



2109



2139,1



2140



2145



2148



2156,1



2156



2157



2164




2175



2182



2185



2188



2191



2237



2240



2436



2437



2438



2439



2528,1




2532



2535



2540



2597



2600



2604



2608